AMENDMENT OF SOLICIT	1. CONTRACT ID CODE	1. CONTRACT ID CODE		PAGE OF PAGES			
AMENDMENT OF SOLICIT		CATION OF CONTRACT		J		1	4
2. AMENDMENT/MODIFICATION NO.	3. EFFECTIVE DATE	4. REQUISITION/PURCHASE REQ. NO.		5. PROJ	ECT N	O.(If applie	cable)
0001	29-May-2003	W81G67-3098-8590					
6. ISSUED BY CODE	DACW37	7. ADMINISTERED BY (If other than item 6)		CODE			
CONTRACTING DIVISION USACE - ST PAUL 190 5TH STREET E ST PAUL MN 55101-1638		See Item 6					
8. NAME AND ADDRESS OF CONTRACTOR	(No. Street County	State and Zin Code)	٧.	9A AMENDMENT OF	SOL	ICITAT	ION NO
6. NAME AND ADDRESS OF CONTRACTOR	(No., Street, County	, State and Zip Code)	Х	9A. AMENDMENT OF DACW37-03-B-0011	301	JCITAL	
			Χ	9B. DATED (SEE ITE) 23-May-2003	M 11))	
				10A. MOD. OF CONTI	RACT	T/ORDER	NO.
		-					
CODE	<u> </u>			10B. DATED (SEE IT	EM 1	.3)	
CODE 11 7	FACILITY CO	DEI PPLIES TO AMENDMENTS OF SOLI	CIT	`ATIONS			
X The above numbered solicitation is amended as set fort				is extended, X is not	extend	led.	
Offer must acknowledge receipt of this amendment p		•		<u>—</u>			
(a) By completing Items 8 and 15, and returning or (c) By separate letter or telegram which includes a RECEIVED AT THE PLACE DESIGNATED FOR T REJECTION OF YOUR OFFER. If by virtue of this a provided each telegram or letter makes reference to the 12. ACCOUNTING AND APPROPRIATION D	reference to the solicitation HE RECEIPT OF OFFER mendment you desire to clude solicitation and this am	on and amendment numbers. FAILURE OF YOU S PRIOR TO THE HOUR AND DATE SPECIF nange an offer already submitted, such change ma	JR A IED y be	ACKNOWLEDGMENT TO B MAY RESULT IN made by telegram or letter,			
12. ACCOUNTING AND AIT NOT KINTTON D	rim (ii required)						
		O MODIFICATIONS OF CONTRACTS					
A. THIS CHANGE ORDER IS ISSUED PUR CONTRACT ORDER NO. IN ITEM 10A.	, <u>.</u>	y authority) THE CHANGES SET FOR	ТН	IN ITEM 14 ARE MAD	E IN	THE	
B. THE ABOVE NUMBERED CONTRACT/ office, appropriation date, etc.) SET FOR					anges	s in payin	g
C. THIS SUPPLEMENTAL AGREEMENT	S ENTERED INTO	PURSUANT TO AUTHORITY OF:					
D. OTHER (Specify type of modification and	d authority)						
E. IMPORTANT: Contractor is not,	is required to si	gn this document and return	cop	pies to the issuing office			
 DESCRIPTION OF AMENDMENT/MODIF where feasible.) Bidders are reminded and encouraged to att Forks North Dakota 	, 0			· ·			
Contract Clause 52.211-10 is amended.							
This amendment highlights a new GAO Decis	sion on the submissi	on of bid bonds.					
Specifications are amended with attachment	"Residential Inspecti	on Report" attached to this amendmen	t.				
Except as provided herein, all terms and conditions of the d 15A. NAME AND TITLE OF SIGNER (Type of						or print)	
19A. NAME AND TITLE OF SIGNER (Type (,, print)	16A. NAME AND TITLE OF CO	1 N 1		1 уре	or brunt)	
15D GOVERN (GEORGE)	150 5	TEL:	D. T. C	EMAIL:	1	D	
15B. CONTRACTOR/OFFEROR	15C. DATE SIGNE	ED 16B. UNITED STATES OF AME	KIC	A	16C.	DATE S	IGNED
(Signature of manage outh		(Signature of Contracting Of	·c: -) m)			
(Signature of person authorized to sign)	I	(Signature of Contracting Of	1106	51 <i>)</i>	I		

SECTION SF 30 BLOCK 14 CONTINUATION PAGE

SUMMARY OF CHANGES

SECTION 00700 - CONTRACT CLAUSES

1. The following contract clause has been modified:

52.211-10 COMMENCEMENT, PROSECUTION, AND COMPLETION OF WORK (APR 1984)

The Contractor shall be required to (a) commence work under this contract within 10 calendar days after the date the Contractor receives the notice to proceed, (b) prosecute the work diligently, and (c) complete the work on Lewis Boulevard Lot within 90 days after Notice to Proceed, and complete the work on Conklin Avenue not later than 120 days after Notice to Proceed. The time stated for completion shall include final cleanup of the premises.

.

(End of clause)

2. NOTICE TO BIDDERS:

The one of the purposes of this amendment is to advise the bidders of a recent bid protest decision by the Comptroller General regarding the validity of bid bonds accompanied by powers-of-attorney that do not contain original certifications. A copy of that decision (Matter of: All Seasons Construction, Inc., B-291166.2, December 6, 2002) is available at http://www.mvp.usace.army.mil/docs/doingbus/GAOB-2911662.pdf in PDF format. That decision is significant because some powers-of-attorney that we considered valid prior to that case may now be invalid. Please note that an invalid power-of-attorney makes the bid bond invalid – an invalid bid bond makes the bid nonresponsive – a nonresponsive bid can not be corrected after bid opening and must be rejected.

Our Bid Schedule Note (13) on Bid Bonds has been updated accordingly and the revised paragraph c is printed below for your reference. Bidders may wish to make this information available to their sureties and bonding agents. Bidders are also advised to submit their bid bond with either: (a) an original power-of-attorney or (b) a power-of-attorney containing an original certification. Bidders doing otherwise bear the risk that their bid will be rejected.

THE BID NOTE 13 CONTAINED IN THE SOLICIATION IS AGAIN PROVIDED:

13. Bid Bonds

- a. It is the responsibility of the bidder to include an acceptable bid guarantee with their bid. This bid note does not provide bidders with an all-inclusive checklist for submitting an acceptable bid bond rather, it provides some "lessons learned" information as to the unacceptability of photocopied bid bonds.
- b. This solicitation requires bidders to submit a bid guarantee along with their bids (see clause 52.228-1). One acceptable form of bid guarantee is a bid bond. For a bid to be responsive, the bid bond accompanying the bid must unequivocally bind the bonding company if it does not, the bid <u>must</u> be rejected as non-responsive. Please note that a non-responsive bid may not be corrected after bid opening to make it responsive it <u>must</u> be rejected. The Contracting Officer has the authority and responsibility to determine whether the bid bond and its accompanying documentation clearly show that the person(s) executing the bid bond on behalf of the surety have the authority to unequivocally bind the bonding company. In order for a bid bond to be acceptable, it must

be accompanied by a valid power-of-attorney issued by the surety (the bonding company, not the insurance agency writing the bond).

c. Photocopied or faxed powers-of-attorney are not acceptable. In order for a power-of-attorney accompanying a bid bond to be acceptable, it must be: (i) an original power-of-attorney (containing all original signatures) or (ii) a copy of a power-of-attorney accompanied by an original certification (original means original signature) by the secretary (or other authorized officer) of the surety stating that the copied power-of-attorney is still in full force and effect as of the date of the certification and has not been revoked. An original signature is one that (I) has been added at the time of the certification and (II) is manually affixed to the power of attorney (not computer generated). The presence of an original seal (a raised, crimped corporate seal or a paper or foil corporate seal that is manually attached) at the certification block of a power-of-attorney is <u>not</u> a substitute for an original signature.

3. The following specifications are amended:

Specification Section 00830

Cover Sheet. To "LIST OF ATTACHMENTS" add Attachment 3. "Residential Inspection Report " (2 pages) which is attached to and is a part of this amendment.

Specification Section 02226

Add the following paragraphs:

"3.2.9 City of Grand Fork Residential Code Requirements

The contractor shall make repairs and replacements as necessary to bring the relocated structure into compliance with the city code. A residential inspection report dated May 14, 2003 is included in Section 00830.

- 3.2.9.1 Chimney. Point and tuck as required.
- 3.2.9.2 Repair, splint or replace "dry rot in approximately 10 joist in SE corner."
- 3.2.9.3 Plumbing. Furnish and install approved S-traps.
- 3.2.9.4 Electrical. Wiring shall be brought to code. All outlets shall be grounded. Bath and kitchen outlets shall be GFCI protected.
- 3.2.9.5 Smoke detectors shall be hard wired and brought to code.
- 3.2.9.6 Raise handrail on 3rd floor to at least 36" high and space vertical rail so that a 4" sphere cannot past through.
- 3.2.9.7 Cover 3rd floor foam insulation with fire retardant material.
- 3.2.9.8 Install latches to all access doors to attic space.

٦.	٠,	y	y,	Ren	191r	coun	ter 1	ton	1n	k1tc	hen
J	• ~	• /	. /	TOP	ull	Coun	LCI I	ιυρ	111	KILC	mon.

3.2.9.9 No action is required on the side door, storms or screens, and third floor fireplace."

(End of Summary of Changes) See Attached two pages.

RESIDENTIAL INSPECTION REPORT

the secondary and the periods

RESIDENTIAL INSPECTION REPORT							
Address: 1502 Lewis Boulevard Property No.: 44-2802-043-00 Zone: R2 Date: May 14, 2003							
Addition: Riverside Park Add	Block: 4	Lot: NORTH	10' OF LOT 15 & ALL	OF Inspector:	Barney S.		
Owner: CITY OF GRAND FORKS	· · ·						
Owner Address: 255 N 4TH ST	•	_ City: <u>GRANI</u>	D FORKS	_ State: ND	ZIp: 58203		
Single Family Home.	Duplex	Town Hous	se . Condo	_			
EXTERIOR ITEMS:	PROBLEMS:		OMMENTS:				
Foundation: Block Concrete Poured Brick	Seepage Holes Bulging Crack	3	fouse will be moved a	and new foundat	tion builf		
Walls: Lap Stucco Aluminum ✓ Brick Shake Panel	Buiging Leaning Needs Painting	C)K				
Roof: Asphalt Wood	Sagging Rottin	ng i	lew roof in 2002		·		
Chimney: ✓ Brick ✓ Metal Block Lined(Clay) Unused Lined(Metal)	Loose Leani Crumbling Improper Connection	ng F	ricks on main chimne ireplace chimney is n	netal	& tucked.		
Porch and Stairs: Handralis	Rotting Unsaf Sagging Shaky	[P	ront porch-some rot-s lear-porch top & boite o 2nd floor porch-som	m plate rotten,s	upport beams		
Doors: ☐Hinge ✓Storm ☐Latch ✓Screens	Holes Missir		ide door into garage e arage	does not meet c	ode to enter		
Windowa: ✓ Storms ✓ Combination ✓ Screens	Broken Rottin Missing Loose Lack of Windows	- 1	ome storms are miss	ing			
Eaves and Trim: Poor Good Fair	Missing Saggi	ng S	outh side soffit needs	a little repair, so	crape & paint		
Yard: ☐Off Street Parking ☐Fence	Old Cars Rubbi		/A				
Accessory Buildings: Single Attached Double Attached Single Detached Double Deta	Shed Other	To be demolished, will not be moved					
INTERIOR ITEMS:	PROBLEMS:	C	COMMENTS:				
Loadbearing: 2 X 10	Leaning Rotting	g D	ry rot in approx. 10 jo	lats in SE come	r 		
Basement Floor: Dirt Concrete	Cracked Seeps	ige	be removed				
Interior Floors:wood,crpt.	☐Rot(Ing ☐Saggir	ng	K		<u> </u>		
Stairs: Handralls	Shaky Unsaf	e Steps O	K .				
Walls and Cellings:	Cracks Loose	ı	K, plaster & sheetroc	k	,		

		120% F.6072			
INTERIOR ELEMENTS:	PROBLEMS:	COMMENTS:			
Doors	Hinge Latch Holes Sagging Missing Trim	OK, panel & hollow core			
Sump Pump: None Interior Exterior	Discharge to Sanitary Sewer Electrical	none			
Plumbing: ✓ Copper ✓ Gelvanized	Cracked Plastic Piping Broken Lack of Running Hot Water	OK, mix. of copper & galvanized water pipes.			
Fixtures: Bath 1: Water Closet Tu Bath 2: Water Closet Tu Bath 3: Water Closet Tu	b Lavatory Shower	Plumbing shall be brought to code, S-traps			
Heating/AC: Source: Central Air Oil Wood Stove Electric Wood Fireplace Gas Gas Fireplace Appliance: Venting: Furnace Conventional Boiler PVC Electric Baseboard	More Than 1 Fuel Source in Chimney Limproper Clearance to Venting Improper Slope in Venting Improper Gas Piping Missing Gas Shut Off Valve	New fireplace on 3rd floor - O clearance Gas line to fire place on 3rd floor must be inspected after move. New boiler in 1997			
Water Heater: ☐ Electric ☐ Gas-PVC ✔ Gas-Conventional	Safety Davices: ✓ Safety Valve ✓ Rellef Piping	ok .			
Electrical: Amp: 200 ✓ 2 Wire Service Location: ✓ 3 Wire	Overloaded Kitchen GFI Open Prayed Basement GFI Fusetat Lack of Adequate Service	Wiring must be brought to code. All autiets to be grounded and bath & kitchen autiets GFCI protected			
Ventilation: ✓Bath ✓Kitchen	Lack of Openable Windows	OK-windows for ventilation Some screens are missing			
	moke Detectors: Each FloorEach Sleeping Room	Smoke detectors will have to meet code when wiring is brought to code			
Egress:	Lack of Dual or Secondary Egress	Will have new basement built to code			

OTHER NOTES:

Repair or replace side door - does not meet code for garage entry

Repair counter top in kitchen

3rd floor guerdrait is 26", cannot be less than 36" in height with vertical reilings spaced so that a 4" sphere cannot pass through 3rd floor eaves have foam insulation-cover with fire retardant material if left as is.

Install latch on all access doors to attic space, cannot be used as storage